



This is to certify that the Quality Management System of:

**North Star Imaging, Inc.**

19875 S. Diamond Lake Road  
Rogers MN 55374  
United States of America

(Central function listed above. See appendix for additional locations)

applicable to:

**The design, manufacture, installation and service of industrial x-ray imaging systems and x-ray imaging services**

has been assessed and approved by  
National Quality Assurance, U.S.A., against the provisions of:

**ISO 9001:2015**

For and on behalf of NQA, USA

Certificate Number: 14874  
EAC Code: 19  
Certified Since: June 13, 2013  
Valid Until: June 7, 2022  
Reissued: June 8, 2019  
Cycle Issued: June 8, 2019



# Certificate of Registration



Appendix to Certificate Number: 14874

**Includes Facilities Located at:**

**North Star Imaging, Inc.**  
Certificate Number 14874  
19875 S. Diamond Lake Road  
Rogers MN 55374  
United States of America

Manufacturing - The Design, Manufacture, Installation, Training and Service of Industrial X-Ray Imaging Systems; Provider of Industrial X-Ray Inspection Services; System Sales Office

**North Star Imaging - EU**  
Certificate Number 14874  
Les Fregates 6  
Hall F Paris Nord II  
13 Rue de la Perdrix  
93290 Tremblay-en-France  
Paris  
FRANCE

Service – Provider of Industrial X-Ray Inspection Services; Provider of System Installations, Training and Preventive Maintenance; System Sales Office

**North Star Imaging - UK**  
Certificate Number 14874  
Instron House  
Coronation Road  
High Wycombe, Buckinghamshire  
High Wycombe HP12 3SY  
United Kingdom

Service – Provider of Industrial X-Ray Inspection Services; System Sales Office

**North Star Imaging, Inc**  
Certificate Number 14874  
362 Elm Street, Unit 9  
Marlborough MA 01752  
United States of America

Service – Provider of Industrial X Ray Inspection Services

Certified Since: June 13, 2013

Valid Until: June 7, 2022

Reissued: June 8, 2019

Cycle Issued: June 8, 2019

# Certificate of Registration



global assurance

Appendix to Certificate Number: 14874

**Includes Facilities Located at:**

**North Star Imaging, Inc.**  
Certificate Number 14874  
16170 Scientific Way  
Irvine CA 62618  
United States of America

Service – Provider of Industrial X-Ray Inspection Services

nqa

Certified Since: June 13, 2013

Valid Until: June 7, 2022

Reissued: June 8, 2019

Cycle Issued: June 8, 2019